

Trouble Shooting

Introduction: TempRite® CPVC materials run more consistently and produce parts with better properties and appearance when they are processed with melt temperatures toward the upper end of their recommended range. The typical molding problems encountered are too low a melt temperature, and a downward trend of melt temperature with time. If the correct screw design is being used (Page 2) experience has repetitively shown that a few critical process parameters tend to force melt temperature down.

- 1. Condition of the chrome plate:** As chrome wears, contact with the base metal exposes the CPVC melt to the element iron (Fe), which catalyzes the decomposition of the CPVC. The tendency for the machine operator, who may be unaware of the condition, is to reduce melt temperature setting to prevent the burning of the material. This will cause poor fusion at the weld lines and weak, poor appearance parts are the result. Under these conditions, high quality parts cannot be produced.
- 2. Small molds in large presses:** Small molds in large presses cause low utilization of barrel capacity (Page 2). This means the CPVC melt resides in the barrel at processing temperatures long enough to initiate decomposition. Again, the typical response

is to lower melt temperature settings to allow the material to process without burning. The result is again, weak knit lines and flow lines.

Run to run repeatability is often blamed on batch to batch variability of TempRite® CPVC. However, operating procedures should be examined first.

- 3. Melt Temperatures:** Melt temperature in the lower end of the recommended range will cause the entire molding process to be more sensitive to variations of any kind.
- 4. Screw RPM:** Variations in screw RPM will drastically alter melt temperature. Once an RPM has been established that yields the correct melt temperature for a given press/mold combination, it should be standardized. It is not reasonable to expect operators to maintain constant RPM settings **without a working tachometer on the machine.**
- 5. Injection Rate:** Injection speed profoundly affects the temperature of the melt. It should be standardized and optimized for each mold/machine combination. If burning occurs in the sprue, runners or gates, the injection rate must be reduced, or the flow passages enlarged.

Problem Solving Guide

Problem	Possible Causes		
	Barrel/Screw/Nozzle	Sprue/Mold	Feed Stock
Short Shots	Injection Pressure Low Injection Time Short Stroke Short Injection Rate Low Melt Temperature Low	Mold Temperature Low Vents Not Working Gates Too Small Sprue, Runners Small Unbalanced Filling	Hopper Empty Hopper Bridging Compound Undried
Burn Streaks in Parts	Injection Speed Too High Melt Temperature Low	Mold Too Cold Gates Too Small Vents Not Working Unbalanced Filling	Compound Undried
<i>Check For Burning in Runners & Sprue</i>			
Burn Streaks in Runners	Nozzle Too Hot Nozzle Too Small Chrome Bad	Sprue Too Small Runners Too Small Runners Rough Poor Radii at Branches	
<i>Check for Burning in Barrel (Air Shots)</i>			
Burning in Barrel	Controller Malfunctioning Screw RPM Too High Screw Too Severe Chrome Plating Bad Back Pressure Too High Shot Size Too Small		Over-Used Regrind Contaminated Regrind
Weak Weld Lines	Melt Temperature Low Injection Pressure Low Packing Pressure Low Cushion Inadequate Injection Speed Low	Vents Not Working Mold Too Cold Mold Release Excessive Gates Too Small Poor Gate Location	Compound Undried
Splay, Silver Streaks, Blisters	Melt Temperature High Injection Speed High Incipient Burning	Mold Too Cold Vents Not Working Gates Too Small	Compound Undried Compound Contaminated Over-Used Regrind
Sink Marks	Packing Pressure Low Packing Time Short Injection Speed Slow Cushion Excessive Cushion Inadequate Nozzle Too Hot Nozzle Too Small	Unbalanced Filling Mold Too Hot Cool Time Inadequate Gates Too Small Sprues, Runners Small Consider Water Quench	
Flow Lines, Delamination	Melt Temperature Low Injection Speed Slow	Mold Too Cold Gates Too Small Gates Rough	Compound Undried
Warping	Packing Pressure Low Melt Temperature Low	Mold Too Hot Cool Time Inadequate Mold Cooling Uneven Consider Cooling Fixture	
Excessive Shrinkage	Melt Temperature Low Packing Pressure Low Injection Speed Low	Mold Too Cold Cooling Time Inadequate Unbalanced Filling	